

Changelog MC-1-U GPS Master Clock

Possible log types:

- [Update instructions] for essential requirements and information about the firmware update procedure
- [Added] for new features
- [Changed] for changes in existing functionality. Improvements should appear under the 'changed' section
- [Removed] for now removed features in this release
- [Fixed] for any bug fixes

[Version 1.01] - 2026-06-17

Update Instructions:

To ensure proper functionality and synchronization, please follow this update sequence when upgrading firmware:

1. Always update the firmware for the Primary Controller first.
2. Once the Primary Controller is updated successfully, proceed further to update the firmware for the Secondary Controller.
3. Before proceeding with the firmware upgrade, please read the firmware update procedure carefully read the firmware update procedure

By following this order, you will ensure a smooth and efficient update process.

FILE NAME	CONTROLLER	VERSION	CHANGELOGS
Version 1.01	PRIMARY	3.05	Removed: 1. Dual SPI Issue 2. IP address limit set (Via serial & LCD) 3. Time zone offset limit Event Time & Event On time Character limit set with only numeric value (i.e. if EW0=0, then ET1=0) 4. IP Address limit set (Via Serial & LCD)
	SECONDARY	2.14	Added: Web Browser (HTTP) Removed: 1. Dual SPI Issue 2. IP address limit set (Telnet) 3. Read write community (Location & Description) Special Char 4. SPI Interrupt 5. IP Address limit set (Via Serial & LCD)