

# ***masibus***<sup>®</sup>

A Sonepar Company



# Thermography

*Fault Detection by Infrared Inspection*

**Masibus Automation And Instrumentation Pvt. Ltd.**

**Address:** B-30, GIDC Electronics Estate, Sector 25, Gandhinagar - 382024, Gujarat, India

**Website:** [www.masibus.com](http://www.masibus.com) | **E-mail:** [sales@masibus.com](mailto:sales@masibus.com) | **Phone:** +91 7923287275-77

## Our Services

Thermography study & health report of the equipment for preventive action.


➤ IR Inspection of MCC / PCC / VFD Panels for hot & cold junction & leak detection

➤ IR Inspection of Furnace Insulation

- ✓ Blast Furnace
- ✓ Reheat Furnace
- ✓ Tempering Furnace
- ✓ ARC Furnace
- ✓ Ladle Furnace
- ✓ Carburizing Furnace

➤ IR Inspection of High Voltage Transmission & Distribution Line


MCC Panel



Furnace



Distribution



VFD Panel



## Industries Served



Power



Oil & Gas



Chemical



Metal



Paper



Fertilizer



Automobile



Glass



Cement

**Masibus Automation And Instrumentation Pvt. Ltd.**

**Address:** B-30, GIDC Electronics Estate, Sector 25, Gandhinagar - 382024, Gujarat, India

**Website:** [www.masibus.com](http://www.masibus.com) | **E-mail:** [sales@masibus.com](mailto:sales@masibus.com) | **Phone:** +91 7923287275-77